Scope of	ope of Work for Property Located at:					4056 North 41st Street			
	Property is: Single Fa	mily	<b>✓</b>	Dupl	ex	□ Other□			
Date:	12/8/2014								
take no respon	sibility for problems discovered	after the	insp	ection	date	The City of Milwaukee, the Redevelopment , or for omissions through error or oversight. ral Block Grant or HOME programs.	-		
Exterior C	Condition Report								
Location Site	Required Work Landscaping	n/a	v	Yes		Note/Comments Self Help	\$	Cost	
	Steps/Handrails	n/a	<b>V</b>	Yes			\$		
	Service walks	n/a	<b>V</b>	Yes			\$		
	Fencing	n/a	V	Yes			\$		
	Parking	n/a	<b>V</b>	Yes			\$		
	Retaining walls	n/a	<b>V</b>	Yes			\$		
	Other	n/a		Yes	<b>V</b>	Patch/replace driveway	\$	950.00	
	Other	n/a		Yes			\$		
Garage	Singles: repair	n/a	V	Yes			\$	_	
	Shingles: Roof over existing	n/a	V	Yes			\$		
	Shingles:Tear off & re-roof	n/a	V	Yes			\$		
	Gutters/downspouts	n/a	<b>√</b>	Yes			\$		
	Flashing	n/a	<b>√</b>	Yes			\$		
	Eaves	n/a		Yes	V		\$	320.00	
	Siding	n/a		Yes	<b>V</b>		\$	1,200.00	
	Doors	n/a		Yes	V		\$	1,300.00	
	Windows	n/a		Yes	V		\$	300.00	
	Slab	n/a	<b>√</b>	Yes			\$		
	Paint	n/a	<b>√</b>	Yes			\$		
	Electrical	n/a	<b>√</b>	Yes			\$		
	Other	n/a		Yes	<b>V</b>	Straighten structure	\$	500.00	
Porches	Roof	n/a	<b>V</b>	Yes			\$		
	Deck-upper	n/a	V	Yes			\$		
	Decklower	n/a	<b>V</b>	Yes			\$		
	Steps/handrails	n/a	V	Yes			\$		
	Ceiling	n/a	V	Yes		-	\$		
	Guardrails	n/a	V	Yes		-	\$		
	Structural	n/a	<b>V</b>	Yes			\$		

\$

450.00

n/a ☑ Yes □

n/a Yes Front stoop

Paint

Other

## House

Chimney	n/a ☑	Yes □	\$
Shingles: repair	n/a ☑	Yes 🗆	\$
Shingles: Roof over existing	n/a ☑	Yes 🗆	\$
Shingles:Tear off & re-roof	n/a ☑	Yes 🗆	\$
Gutters/downspouts	n/a ☑	Yes 🗆	\$
Flashing	n/a □	Yes 🗸	\$ 500.00
Eaves	n/a ☑	Yes 🗆	\$
Siding	n/a □	Yes 🗸	\$ 2,400.00
Storm Doors	n/a □	Yes 🗸	\$ 350.00
Prime ("main") Doors	n/a ☑	Yes 🗆	\$
Storm Windows	n/a ☑	Yes 🗆	\$
Prime ("main") Windows	n/a □	Yes 🔽	\$ 3,720.00
Paint	n/a ☑	Yes 🗆	\$
Foundation	n/a ☑	Yes 🗆	\$
Electrical	n/a ☑	Yes 🗆	\$
Other	n/a □	Yes	\$
Other	n/a □	Yes 🗆	\$
Other	n/a □	Yes 🗆	\$
Other	n/a □	Yes	\$

Exterior: Estimated Cost:\* \$ 11,990.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	Unit: Entire unit (single family) Upper unit of duplex	<a> </a>		Lower unit of duplex Other		
Mechanical Heating	Required Work					
	Repair/replace boiler	n/a ☑	Yes 🗆	_		\$
	Repair radiation	n/a ☑	Yes 🗆			\$
	Repair/replace furnace	n/a □	Yes ✓			\$ 3,100.00
	Repair ductwork	n/a ☑	Yes 🗆			\$
	Replace thermostat	n/a ☑	Yes 🗆			\$ 
	Repair/replace grilles	n/a ☑	Yes 🗆			\$
Electrical	Tune boiler/furn. insp ht exchang	en/a ☑	Yes 🗆			\$
Licotrioui	Repair/replace receptacles	n/a ☑	Yes 🗆			\$
	Repair/replace switches	n/a ☑	Yes 🗆			\$
	Repair/replace fixtures	n/a ☑	Yes 🗆			\$
	Install outlets and circuits	n/a ☑	Yes 🗆			\$
	Install outlets and circuits	n/a □	Yes ✓	GFCI		\$ 600.00
	Install outlets and circuits	n/a ☑	Yes 🗆			\$
	Install outlets and circuits	n/a ☑	Yes 🗆			\$
	Upgrade service	n/a ☑	Yes □			\$ 
	Other	n/a □	Yes 🗆			\$
Plumbing	Other	n/a 🗆	Yes 🗆			\$
Plumbing	Repair/replace kitchen sink	n/a □	Yes 🗆			\$
	Repair/replace kitchen sink fauce	ein/a □	Yes 🗆			\$
	Repair/replace tub	n/a □	Yes 🗆			\$
	Repair/replace tub faucet	n/a □	Yes 🗆			\$
	Repair/replace toilet	n/a □	Yes 🗆			\$
	Repair/replace lavatory	n/a □	Yes 🗆			\$
	Repair/replace lavatory faucet	n/a □	Yes 🗆			\$
	Repair/replace wash tub	n/a □	Yes 🗆			\$
	Repair/replace wash tub faucet	n/a □	Yes ☑			\$ 300.00
	Unclog piping:	n/a □	Yes 🗆			\$
	Repair drain/waste/vent piping	n/a □	Yes 🗆			\$
	Repair water piping	n/a □	Yes 🗆			\$
	Repair/replace water heater	n/a □	Yes 🗆			\$
	Other	n/a □	Yes 🗆			\$
	Other	n/a □	Yes □			\$

Windows					
	Replace broken glass	n/a ☑	Yes [		\$ 
_	Repair or replace sash	n/a <u></u> ✓	Yes [		\$ 
Doors	Repair or replace doors	n/a □	Yes [		\$ 400.00
	Repair or repl. locks/latches	n/a □	Yes [	Self Help	\$ 110.00
Walls/Ceiling	gs Repair or repl. @ defective	n/a □	Yes [		\$ 1,400.00
Paint	Repair or repl. @ defective	n/a _□	Yes [		\$ 1,140.00
Fire Safety	Install smoke/CO alarm:bsmt.	n/a □	Yes 🗔	Self Help	\$ 55.00
	Install smoke/CO alarm: 1st flr.	n/a □	Yes 🗔	Self Help	\$ 55.00
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes 🕓	Self Help	\$ 110.00
Handrails	Repair/replace defective	n/a ☑	Yes [	Self Help	\$
Stairs	Repair defective	n/a ☑	Yes [		\$
Floors	Repair defective	n/a □	Yes 🕓	222	\$ 600.00
Other		n/a □	Yes 🖸	R/R tile tub surround	\$ 275.00
		n/a □	Yes [		\$
		n/a □	Yes [		\$
		1.1	1	· -	
				Interior: Estimated Cost:	\$ 8,145.00
				Total Exterior and Interior Cost:*	\$ 20,135.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Inspected by: Martin Kleiber Date: 12/8/2014

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 West Mill Road.